



[News](#) > [BUILDER Release Notes](#) > [SMS BUILDER 3.3.3 Release Notes](#)

SMS BUILDER 3.3.3 Release Notes

2019-03-12 - Gershwin Marks - [Comments \(0\)](#) - [BUILDER Release Notes](#)

BUILDER 3.3.3:

- Feature: Cost factors for "High Security" and "Additional Access" have been added
- Enhancement: "Read-only" option added to administration interface for editing user accounts
- Enhancement: Facility "Systems at a Glance" tab now displays checkout information
- Enhancement: System page now displays checkout information when hovering over the lock icon
- Enhancement: Data in facility column in Site screen's "Facility Summary" tab now links directly to building screen
- Fix: Distress Survey Inspection Report by Section now honors correct Unit of Measure when user has checked the Alternative UM box
- Fix: Deleting a section now immediately removes its condition data

ROOFER 3.3.3:

- Enhancement: Fiscal Year data has been added to several reports
- Fix: Multi-Core Insulation inspections are now saved
- Fix: MR&R Roof Section Analysis and Roof Section Cost Analysis reports now display repair/replace ratio correctly