

Updates to CERL hosted sites will be scheduled with individual customer leads. Self-hosted customers and licensing partners can receive installers on or after the release date.

BUILDER 3.6.8.3 Update, 06/30/2026

NEW FEATURES:

- The inspection-adjusted curve now properly intersects inspection points in edge cases, when components are inspected to degrade quickly and early.
- No change is made to the inspection-adjusted Service Life.
- Alpha factor is clamped at 0 instead of 1.
- Updated handling for extreme edge cases.